## IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re patent of:

Confirmation No.: 7577

NGUYEN et al.

Art Unit: 2183

Patent. No.: 7,162,610

Examiner: Daniel H. Pan

Issued: January 9, 2007

Atty. Docket: 1397.028000F

For: High-Performance, Superscalar-**Based Computer System With Out-Of-Order Instruction Execution** 

## **Request for Certificate of Correction Under 37 C.F.R. § 1.323 For Applicant's Mistake**

Attn: Certificate of Correction Branch

Commissioner for Patents PO Box 1450 Alexandria, VA 22313-1450

Sir:

It is hereby requested that a Certificate of Correction under 37 C.F.R. § 1.323 be issued for the above-captioned United States Patent. This Certificate of Correction is being requested due to a mistake which appears in the printed patent. The mistake made by Applicants is of a clerical or typographical nature, or of a minor character. Patentees submit that correction of this error does not introduce new matter.

Specifically, the printed patent contains the following error for which a Certificate of Correction is respectfully requested:

At column 32, line 41, "TBL modified" should be replaced with --TLB modified--.

## Remarks

The above-noted corrections do not involve such changes in the patent as would constitute new matter or would require reexamination.

A completed Form PTO/SB/44 accompanies this request, with the above-noted corrections printed thereon. Accordingly, a Certificate of Correction is believed proper and issuance thereof is respectfully requested.

This request is accompanied by payment of the fee set forth in 37 C.F.R. § 1.20(a). The Commissioner is hereby authorized to charge any fee deficiency, or credit any overpayment, to our Deposit Account No. 19-0036.

Respectfully submitted,

STERNE, KESSLER, GOLDSTEIN & FOX P.L.L.C.

Donald J. Featherstone Attorney for Patentees Registration No. 33,876

Date: February 8, 2008

1100 New York Avenue, N.W. Washington, D.C. 20005-3934 (202) 371-2600

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

(Also Form PTO-1050)

## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

CERTIFICATE OF CORRECTION					
	7.172.710	Page _	1	_ of _	1_
PATENT NO. :	7,162,610				
APPLICATION NO.:	10/660,671				
ISSUE DATE :	January 9, 2007				
INVENTOR(S) :	Le Trong NGUYEN				
It is certified to is hereby corrected	that an error appears or errors appear in the above-identified patent and the das shown below:	at said	Lette	rs P	atent
At column 32, line 41, "TBL modified" should be replaced withTLB modified					

MAILING ADDRESS OF SENDER (Please do not use customer number below):

Sterne, Kessler, Goldstein & Fox P.L.L.C.

1100 New York Avenue, N.W.

Washington, DC 20005-3934

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.